

Q1



a)-Kennedy Key :

For heavy duty installation

- woodruff Key :

suitable for very small torque to avoid troublesome fitting. It does no tipping or rolling.

well adapted to tapered shafts.




b)

$$P = ??$$

$$\sigma = 100 \text{ MPa}$$

$$d = 20 \text{ mm}$$



$$T = F \cdot l = F \cdot 100 \text{ N-mm}$$

$$F_p = \frac{F}{4}$$

$$r_1 = 300 \text{ mm} \quad r_2 = 100 \text{ mm}$$

$$r_4 = 300 \text{ mm} \quad r_3 = 100 \text{ mm}$$

$$\theta_1 = \theta_2 = 180^\circ \quad \theta_3 = \theta_4 = 0^\circ$$

the worst rivet is rivet 1       $r_1 = 300 \text{ mm}$   
 $\theta_1 = 180^\circ$

$$F_1 = \frac{T r_1}{\sum_{i=1}^n r_i^2} = \frac{F \cdot 100 \cdot 300}{2(300)^2 + 2(100)^2} = 0.15F$$

$$\begin{aligned} F_{s1} &= \sqrt{F_p^2 + F_1^2 - 2F_p F_1 \cos \theta_1} \\ &= \sqrt{\left(\frac{F}{4}\right)^2 + (0.15F)^2 - 2 \cdot \frac{F}{4} \cdot 0.15F \cos 180^\circ} \\ &= 0.4F \end{aligned}$$


$$\tau = \frac{F_{s1}}{A}$$

$$100 = \frac{0.4F}{\frac{\pi}{4}(20)^2} \quad \therefore F = 78539.82 \text{ N}$$


Q2

## a) Types of fillet welding

### ① Lap joint




### ③ corner joint



### ② Butt joint

#### a) square butt joint



#### b) single V-butt joint



#### c) single U-butt joint



#### d) double V- ~ ~

#### e) double U- ~ ~

### ④ Edge joint



### ⑤ T-joint



$$\bar{x} = \frac{b^2}{2b+d} = \frac{(50)^2}{2*50+100} = 12.5 \text{ mm} \quad \text{مطبع}$$

$$\bar{y} = \frac{d}{2} = \frac{100}{2} = 50 \text{ mm}$$

$$A = 0.707 h (2b + d)$$

$$= 0.707 h (2*50 + 100) = 141.4 h \text{ mm}^2$$

$$J_u = \frac{8b^3 + 6bd^2 + d^3}{12} - \frac{b^4}{2b+d}$$

$$= \frac{8*(50)^3 + 6*50*(100)^2 + (100)^3}{12} - \frac{(50)^4}{2*50+100}$$

$$= 385416.667 \text{ mm}^4$$

$$T = F * \ell = 60 * 10^3 * (150 + 50 - 12.5)$$

$$= 11250000 \text{ N.mm} = 11.25 * 10^6 \text{ N.mm}$$

$$\bar{q}_p = \frac{F}{A} = \frac{60 * 10^3}{141.4 h} = \frac{424}{h}$$

$$r_1 = r_2 = \sqrt{(50)^2 + (37.5)^2}$$

$$= 62.5 \text{ mm}$$

$$r_3 = r_4 = \sqrt{(50)^2 + (12.5)^2}$$

$$= 51.54 \text{ mm}$$


$$\alpha = \tan^{-1} \frac{50}{37.5} = 53.13^\circ$$

$$\theta_1 = \theta_2 = 180 - \alpha = 126.87^\circ$$

$$\beta = \tan^{-1} \frac{50}{12.5} = 75.96^\circ$$

$$\theta_3 = \theta_4 = 75.96^\circ$$

The worst point is 1 or 2



for point ①

$$\zeta_{s1} = \frac{Tr}{J} = \frac{11.25 * 10^6 * 62.5}{0.707h * 385416.667}$$
$$= \frac{2580.37}{h}$$

$$T_{max} = \sqrt{\zeta_p^2 + \zeta_{s1}^2 - 2\zeta_p \zeta_{s1} \cos \theta_1} \leq T_{all}$$

$$\sqrt{\left(\frac{424}{h}\right)^2 + \left(\frac{2580.37}{h}\right)^2 - 2\left(\frac{424}{h}\right)\left(\frac{2580.37}{h}\right) \cos 126.8}$$

$$\frac{2854}{h} \leq 140$$

$$mm \quad 20.39 \leq h$$

Q3

- a) The disadvantages of using belt drive are:-
- ① limited power range (compared with gears).
  - ② short life.
  - ③ can't withstand high temperature.

b) V-belt

$$N = ?? \quad \text{power} = 2000 \text{ Watt}$$

$$n_1 = 900 \text{ rpm}$$

$$c = 1500 \text{ mm} \quad d_2 = 400 \text{ mm}$$

$$d_1 = 200 \text{ mm}$$

$$\mu = 0.3 \quad W = 11 * 10^3 \frac{N}{m^3} \cdot \frac{N}{m^3}$$

$$A = 140 \text{ mm}^2$$

$$\beta = \frac{38}{2} = 19^\circ \quad K_s = 1$$

$$\sigma_{all} = 2.5 \text{ MPa}$$

Soln

$$\theta_1 = 180 - 2 \sin^{-1} \frac{d_2 - d_1}{2c}$$

$$= 180 - 2 \sin^{-1} \frac{400 - 200}{2 * 1500} = 172.35^\circ$$

$$V = \frac{\pi d_1 n_1}{60} = \frac{\pi * 200 * 900}{60} * 10^{-3} = 9.42 \text{ m/s}$$

$$F_1 = \sigma_{all} A = 2.5 * 140 = 350 \text{ N}$$

$$F_C = \frac{W}{g} V^2 = \frac{11 * 10^3 * 140 * 10^6}{9.8} * (9.42)^2 = 13.94 \text{ N}$$

$$\frac{F_1 - F_C}{F_2 - F_C} = e^{\mu \theta} \quad \text{for V-belt} \quad \mu_e = \frac{\mu}{\sin \beta}$$

$$F_2 = F_C + \frac{F_1 - F_C}{e^{\mu \theta}} = 13.94 + \frac{350 - 13.94}{\frac{0.3 * 172.35 * \frac{\pi}{180}}{e^{\mu \theta}}} = 34.96 \text{ N}$$

$$\text{power} = K_s (F_1 - F_2) * V * N$$

$$2000 = 1 * (350 - 34.96) * 9.42 * N$$

$$N = 0.6739$$

$$\approx 1$$